

## - Site Report -

Date: January 10, 2012 IRD Sales Order: 11167

To: Cindy Mantie From: Bryan Knight

Project Name/Location: LTPP I-25 N MP 35, NM

Service Date(s): April 19 2011

**Job Description: Maintenance Visit** 

## **Work Completed:**

• Performed visual inspection of roadway and inroad sensors. Road condition and Sensors good.

 Recorded Electrical readings of The Kistlers, Loops, Battery, and Solar Charging System. All reading within normal.

Performed general housekeeping on Equipment Cabinet.

Logged onto Isinc and verified system is operating normally.



Ph: (306) 653-6600 Fax: (306) 242-5599 <u>www.irdinc.com</u>



Schedule Include Estimate to Complete (on-track, ahead, behind):

Parts Used: None

**Pre-mature Equipment Failure:** 

Mileage / Travel Time: Total Travel: 12 hrs Total Onsite: 2hrs

**Safety Concerns: None** 

**Issues Related to Sub-Contractors:** 

Other Notes:

## **Action Items:**

Item	Action Required	Ownership
1.		
2.		
3.		
4.		